

**THE ARGEN CORPORATION**

## Alloy Specification Sheet

## ARGENCO 60S

Color: YELLOW      Type: 4      ADA Classification: HIGH NOBLE (HN)      PGM: 63.51%

## Metal Content %

Au	Pd	Ag	Ir	In	Cu	Zn
60	3.5	21.75	x	x	13.49	1

'x' denotes a content of less than one percent

## Thermal Properties

Melting Range	Casting Temperature	Density g/cm <sup>3</sup>
1580-1660 °F	1850 °F	13.7
860-905 °C	1010 °C	

## Mechanical Properties

Vickers Hardness (VHN)		Yield Strength N/mm <sup>2</sup> (0.2% Offset)		Modulus of Elasticity (GPa)	Elongation %	
Soft	Hard	Soft	Hard	97	Soft	Hard
180	270	366	662			25

**PROCESS****INSTRUCTIONS FOR USE**

## Modeling

Maintain a minimum wax thickness of 0.3 to 0.4 mm.

## Spruing (Single Crowns)

Use direct sprues, 8-10 gauge, (3.3-2.6 mm diameter) and 1/2 in. (12 mm) long with adequate reservoirs. There should be no more than 1/4 in. (6 mm) of investment from the top of the pattern to the top of the investment.

## Spruing (Multi-Units &amp; Bridges)

Use a 6 gauge (4.1 mm diameter) runner bar, connecting the units to the bar with 10 gauge (2.6 mm diameter) sprues 1/8 in. (3 mm) long and joining the bar to the sprue base with 8 gauge (3.3 mm diameter) and 1/2 in. (12 mm) long sprues coming from a domed central entry point. There should be no more than 1/4 in. (6 mm) of investment from the top of the pattern to the top of the investment.

Alloy Quantity	13.7g/cm * (Wax Weight) = Required Alloy Quantity.
Investing	Use debubbler and blow off any excess before investing. Do not preheat Cristobolite investment above 1290°F/700°C. Recommended Investment: Gypsum or Phosphate Bonded Follow the manufacturer's instructions.
Burnout	After adequate set-up time, place the ring(s) in a room temperature oven and raise the temperature to 700 °C / 1290 °F, hold for 1 hour plus 10 minutes for each additional ring. If you are using a rapid fire investment, follow the manufacturer's instructions.
Reusing Cast Alloy	Use only clean buttons and at least 35 percent new alloy.
Crucible Type	Graphite / Ceramic
Torch Casting	Crown & Bridge Alloys can be cast with compressed air and natural gas using a borax flux for optimum results.
Induction or Electrical Casting	For gold-based alloys, use a graphite lined crucible and a casting temperature of at least 212°F/100°C over the liquidus temperature. Every casting machine is different. The casting temperature may require adjustment based upon the alloy and the amount of metal being cast.
Cooling	Either allow the casting ring to cool to room temperature for self hardening, or quench the casting ring in water after the alloy glows dull red to soften.
Divesting and Cleaning	Divest and sandblast with 50 micron aluminum oxide, be careful of margins.
Pickling	Any gold pickling solution may be used for the gold-based alloys.
Soldering	Check that the solder joints are sufficiently large (6-9 mm <sup>2</sup> ). Soldering gap approximately 0.05-0.2 mm. The soldering surfaces should be parallel and pre-polished. Allow the soldered case to cool slowly after soldering.
Recommended Solder	Use: LO / 585
Hardening	Heat Treat for 15 min. at 350°C / 662 °F
Softening	
Laser Wire	

Polishing

Polish with any conventional polishing brushes and felt wheels using Tripoli ,rouge and tin oxide. Soft, medium bristles, chamois, or rag wheels are acceptable.

16-Apr-2009